

FIG. 1

2/5




FIG. 2

90

Redundant Interface Line Card Details - Chassis 1, Slot 7

System: 192.168.2.94

Active Port

Primary

91

Secondary Switch Occurred

Yes

92

SONAR

Disabled

93

Mode

Dynamic Recovery Mode

Mode Control

Select A/B

Select A

96

Auto Restore Primary Circuit

Enabled

Link Pulse Control

Disabled

Redundant Transmission

Enabled

LOA Switchover Time [secs]

10

20

30

99

OK

Apply

Cancel

FIG. 3




FIG. 4




FIG. 5